Jackal Calibration - Quick Start Guide



Press the **Pages** button until Setup is displayed on the bottom of the screen, then press the button below **Setup** to select the setup screen.



Use the **Up** or **Down** arrows to highlight the Inputs, then press the button below **Select.**



Use the **Up** or **Down** arrows to highlight the Input number you require, then press the button below **Select.**



Use the **Down** arrow to highlight Target Number, then Start will appear**.** press the button below **Start** to start the calibration process.



The Meas, pulses will start to count as the product is dispensed. Dispense the required amount and then press the button below **Stop.**



The Target now changes to Actual. Measure the amount of product you collected then press the button below **Edit** to enter the collect weight.



Use the **Up/Down/Left and Right** arrows to add the measured weight. Then press the button below **Exit** to accept the measured weight.



Press the button below **CALC** and the new calculated manual ratio will be displayed.

Press **Exit** to accept the new Manual Ratio or if you are not happy with the calculated number, then press **Start** to restart the calibration.